

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 6621	Main Street: MINERAL_SPRINGS_RD	Cross Street: NEAL_RD	Location: NW
ADA ID: 52342D8D3B8C	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 20	

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.
Grind Gutter Lip.**

Surveyor Notes:

DAMAGED LT FL

PROW/ADA:

R304.5.3, R304.2.3, R302.7.2

Street 1 Name	MINERAL SPRINGS RD
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Total Cost: \$ 1800.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	41.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	54.0	No	Grade Break Slope (%)	6.2
Yes	Ramp Slope (%)	6.4	Yes	Grade Break XSlope (%)	0.5
Yes	Ramp XSlope (%)	1.8			
Yes	Flare Type LT	N/A	No	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	55.5	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	55.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.8	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.7	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	N/A	Yes	DWS Offset LT (in)	24.0
N/A	Shared Landing?	Yes	Yes	DWS Offset RT (in)	0.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	4.5
No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	3.6
N/A	Painted X Walk1?	Yes		Road Slope (%)	5.7
	X Walk 1 Direction	To SW		Road X Slope (%)	5.9
	X Walk 1 Width (in)	114.0		Clear Space?	Yes
	X Walk 1 Slope (%)	5.7	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	5.9	Yes	Storm Grate/Utility Hazard?	No
Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	N/A

