

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025398Main Street:E\_ARROWOOD\_RDCross Street:S\_OAK\_MARKETPLACE\_DRLocation:NEADA ID: 5258E9123B41Ramp Type:Directional1Initial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



| Street 1 Name           | S OAK MARKETPLACE DR |
|-------------------------|----------------------|
| Stop Condition-Street 1 | StopSign             |
| Street 2 Name           | N/A                  |
| Stop Condition-Street 2 | N/A                  |

| ,              | Possible Solution             |        | r leid Measurements/Component Compilance |       |                             |                             |      |  |  |
|----------------|-------------------------------|--------|------------------------------------------|-------|-----------------------------|-----------------------------|------|--|--|
|                | Possible Solutions:           | Comp   | Compliance Description                   |       | Data Compliance Description |                             |      |  |  |
| S.             | Remove & Replace Entire Ramp. | N/A    | Ramp Length (in)                         | 89.0  | N/A                         | Grade Break?                | N/A  |  |  |
| -              | •                             | Yes    | Ramp Width (in)                          | 57.5  | N/A                         | Grade Break Slope (%)       | 0.0  |  |  |
|                |                               | No     | Ramp Slope (%)                           | 16.9  | N/A                         | Grade Break XSlope (%)      | 0.0  |  |  |
| ě              |                               | Yes    | Ramp XSlope (%)                          | 2.0   |                             |                             |      |  |  |
|                |                               | N/A    | Flare Type LT                            | N/A   | N/A                         | Flare Type RT               | N/A  |  |  |
|                |                               | N/A    | Flare Slope LT (%)                       | N/A   | N/A                         | Flare Slope RT (%)          | 0.0  |  |  |
|                | Surveyor Notes:               | N/A    | Flare Traversable LT?                    | N/A   | N/A                         | Flare Traversable RT?       | N/A  |  |  |
| į              | N/A                           | N/A    | Landing Length (in)                      | 0.0   | N/A                         | DWS Provided?               | N/A  |  |  |
|                |                               | N/A    | Landing Width (in)                       | 0.0   | N/A                         | DWS Contrast?               | N/A  |  |  |
| V              |                               | N/A    | Landing Slope (%)                        | 0.0   | N/A                         | DWS Length (in)             | N/A  |  |  |
| 200            |                               | N/A    | Landing X Slope (%)                      | 0.0   | N/A                         | DWS Full Width?             | N/A  |  |  |
| g <sub>i</sub> | PROW/ADA:                     | N/A    | Landing Curb? (Y/N)                      | N/A   | N/A                         | DWS Offset LT (in)          | N/A  |  |  |
|                | R304.2.2                      | N/A    | Shared Landing?                          | N/A   | N/A                         | DWS Offset RT (in)          | N/A  |  |  |
| 1              |                               | N/A    | Gutter Ponding?                          | 0.0   | N/A                         | Gutter Slope (%)            | N/A  |  |  |
| 2000           |                               | N/A    | Gutter Lip Ht (in)                       | 0.0   | N/A                         | Gutter X Slope (%)          | N/A  |  |  |
| 1              |                               | N/A    | Painted X Walk1?                         | Yes   |                             | Road Slope (%)              | 3.5  |  |  |
|                |                               |        | X Walk 1 Direction                       | To W  |                             | Road X Slope (%)            | 11.5 |  |  |
|                |                               |        | X Walk 1 Width (in)                      | 122.0 |                             | Clear Space?                | N/A  |  |  |
|                |                               |        | X Walk 1 Slope (%)                       | 3.5   | N/A                         | Clear Space to XWalk (in)   | N/A  |  |  |
|                |                               |        | X Walk 1 X Slope (%)                     | 11.5  | N/A                         | Storm Grate/Utility Hazard? | N/A  |  |  |
|                |                               | N/A    | Ramp inside XWalk1?                      | Yes   |                             | Storm Grate/Utility Type    |      |  |  |
|                |                               | N/A    | Any Obstructions?                        | N/A   |                             |                             | N/A  |  |  |
|                | Total Cost: \$ 1              | 600.00 | Obstruction Type                         |       | Yes                         | Surface Condition? (G/P)    | Good |  |  |
|                |                               |        |                                          | N/A   | N/A                         | Curb Slope (%)              | 2.6  |  |  |
|                |                               |        |                                          |       |                             |                             |      |  |  |





