

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10015093	Main Street: THE_PLAZA	Cross Street: LAKE_DR	Location: NW
ADA ID: 526132103006	Ramp Type: Para	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 2.75	
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

**Remove & Replace Entire Ramp.
Gutter Ponding Observed.**

Surveyor Notes:

N/A

PROW/ADA:

**R304.5.3, R304.2.2-Perp, R304.3.2-
Para, R305.1.4, R305.2, R302.7**

Total Cost: \$ 2100.00

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length LT (in)	90.0	N/A	Ramp Length RT (in)	71.0
Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	59.0
Yes	Ramp Slope LT (%)	5.5	Yes	Ramp Slope RT (%)	5.5
No	Ramp XSlope LT (%)	2.7	Yes	Ramp XSlope RT (%)	0.6
Yes	Landing Length (in)	70.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	59.0	Yes	DWS Contrast?	Yes
No	Landing Slope (%)	3.9	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.7	No	DWS Full Width?	No
N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	7.5
N/A	Shared Landing?	No			
No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	0.8
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.2
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.9		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	Yes
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	5.5

Street 1 Name	THE PLAZA
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

