


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 20057		Main Street: ASSEMBLY_ST		Cross Street: BULFINCH_RD		Location: SE											
ADA ID: 5270752E7EEB		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 13.75									
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance													
<div></div> <div>Street 1 NameBULFINCH RD</div> <div>Stop Condition-Street 1StopSign</div> <div>Street 2 NameN/A</div> <div>Stop Condition-Street 2N/A</div>				Possible Solutions:		Compliance		Description		Data		Compliance		Description		Data	
				Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	91.0		N/A	Grade Break?	N/A					
						Yes	Ramp Width (in)	60.0		N/A	Grade Break Slope (%)	0.0					
						No	Ramp Slope (%)	9.4		N/A	Grade Break XSlope (%)	0.0					
						No	Ramp XSlope (%)	3.6									
						N/A	Flare Type LT	N/A		N/A	Flare Type RT	N/A					
						N/A	Flare Slope LT (%)	N/A		N/A	Flare Slope RT (%)	0.0					
						N/A	Flare Traversable LT?	N/A		N/A	Flare Traversable RT?	N/A					
						N/A	Landing Length (in)	0.0		N/A	DWS Provided?	N/A					
						N/A	Landing Width (in)	0.0		N/A	DWS Contrast?	N/A					
						N/A	Landing Slope (%)	0.0		N/A	DWS Length (in)	N/A					
						N/A	Landing X Slope (%)	0.0		N/A	DWS Full Width?	N/A					
						N/A	Landing Curb? (Y/N)	N/A		N/A	DWS Offset LT (in)	N/A					
		N/A	Shared Landing?	N/A		N/A	DWS Offset RT (in)	N/A									
		N/A	Gutter Ponding?	0.0		N/A	Gutter Slope (%)	N/A									
		N/A	Gutter Lip Ht (in)	0.0		N/A	Gutter X Slope (%)	N/A									
		N/A	Painted X Walk1?	No			Road Slope (%)	2.5									
			X Walk 1 Direction	To N			Road X Slope (%)	1.1									
			X Walk 1 Width (in)	N/A			Clear Space?	N/A									
			X Walk 1 Slope (%)	2.5		N/A	Clear Space to XWalk (in)	N/A									
			X Walk 1 X Slope (%)	1.1		N/A	Storm Grate/Utility Hazard?	N/A									
		N/A	Ramp inside XWalk1?	N/A			Storm Grate/Utility Type										
		N/A	Any Obstructions?	N/A				N/A									
			Obstruction Type			Yes	Surface Condition? (G/P)	Good									
						N/A	Curb Slope (%)	6.5									
		Total Cost:	\$	1600.00													

