



Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 12078	Main Street: MARLOWE_AV	Cross Street: HIGHLAND_ST	Location: NE
ADA ID: 5274EE3F1D91	Ramp Type: Combination1	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	N/A	N/A	Ramp Length RT (in)	35.0
			N/A	Ramp Width LT (in)	N/A	No	Ramp Width RT (in)	47.0
			N/A	Ramp Slope LT (%)	N/A	Yes	Ramp Slope RT (%)	5.4
			N/A	Ramp XSlope LT (%)	N/A	Yes	Ramp XSlope RT (%)	1.8
			N/A	Ramp Length (in)	52.0	Yes	Ramp Slope (%)	3.2
			No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	5.1
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	Surveyor Notes:		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	NO LT SW, RP < 5%		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	4.1		X Walk 2 X Slope (%)	N/A	
			Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A		Clear Space?	N/A	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstruction?	N/A	
						Obstruction Type	N/A	
								N/A
						N/A	Storm Grate/Utility Hazard?	N/A
							Storm Grate/Utility Type	N/A
								N/A
						Yes	Surface Condition? (G/P)	Good
							Curb Slope (%)	10.2

