

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30613 Main S	Main Street: GOLF_LINKS_DR		Cross Street: PROVIDENCE_RD				NW
ADA ID: 5294CFE825EE Ramp	Type: Combination1	Initial Pass/F	ail: Fail Overall	Complian	nce: N	o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
Possible Solutions:						liance Description	Data
	Remove & Replace Entire Ramp		Ramp Length LT (in)	56.0	N/A	Ramp Length RT (in)	62.0
		Yes	Ramp Width LT (in)	61.0	Yes	Ramp Width RT (in)	60.0
		Yes	Ramp Slope LT (%)	6.2	Yes	Ramp Slope RT (%)	7.8
		Yes	Ramp XSlope LT (%)	1.3	Yes	Ramp XSlope RT (%)	1.0
	2	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	10.8
	<u>A.</u>	Yes	Ramp Width (in)	60.0	Yes	Ramp XSlope (%)	2.8
	Surveyor Notes:	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	s N/A	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
COLF LINKS DR		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
TT T		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	PROW/ADA:	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	<b>R304.2.2</b>	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	5	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name Signa	 	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1 GOLF LINKS DF		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
Street 2 Name N/A	A		X Walk 1 Direction	To S		X Walk 2 Direction	N/A
Stop Condition-Street 2 N/A	A		X Walk 1 Width (in)	112.0		X Walk 2 Width (in)	N/A
			X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A
			X Walk 1 X Slope (%)	2.9		X Walk 2 X Slope (%)	N/A
	Total Cost: \$ 1	800.00 N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	N/A		Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A







N/A

N/A

Yes

Any Obstruction?

Obstruction Type

Curb Slope (%)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

N/A

N/A

N/A

1.1

Good