


Access Compliance Report

Public Rights-of-Way (Curb Ramps)

Intersection ID: 6263	Main Street: W_SUGAR_CREEK_RD	Cross Street: RUMPLE_RD	Location:	SE
ADA ID: 52A81F7E45D0	Ramp Type: Combination2	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length LT (in)	26.5	N/A	Ramp Length RT (in)	N/A
			Yes	Ramp Width LT (in)	56.0	N/A	Ramp Width RT (in)	N/A
			Yes	Ramp Slope LT (%)	5.6	N/A	Ramp Slope RT (%)	N/A
			No	Ramp XSlope LT (%)	6.3	N/A	Ramp XSlope RT (%)	N/A
			N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.0
			Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	0.7
	Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Not Found, R304.2.2, R304.5.3		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
Street 1 Name		StopSign		X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
Stop Condition-Street 1		W SUGAR CREEK RD		X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 2 Name		N/A		X Walk 1 Slope (%)	0.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2		N/A		X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	N/A
Total Cost:		\$ 1600.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
				Road Slope (%)	N/A		Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
						N/A	Any Obstruction?	N/A
							Obstruction Type	N/A
						N/A	Storm Grate/Utility Hazard?	N/A
							Storm Grate/Utility Type	N/A
						Yes	Surface Condition? (G/P)	Good
							Curb Slope (%)	16.2

