

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

50.0

56.0

7.0

2.4

5.7

0.9

N/A

No

To N

N/A

0.7

2.5

N/A

N/A

Intersection ID: N/A Main Street: HICKORY_GROVE_RD Cross Street: VALLEYVIEW_DR Location: SW

ADA ID: 532B82572B31 Ramp Type: Combination1Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

StopSign VALLEYVIEW DR None HICKORY GROVE RD Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description N/A Ramp Length RT (in) N/A Ramp Length LT (in) 54.0 Yes Ramp Width LT (in) 56.0 Yes Ramp Width RT (in) Yes Ramp Slope LT (%) 5.7 Yes Ramp Slope RT (%) Ramp XSlope LT (%) 6.3 No Ramp XSlope RT (%) No N/A Ramp Length (in) 36.0 Yes Ramp Slope (%) 42.0 Yes Ramp XSlope (%) No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To E X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) 3.2 X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 1.4 X Walk 2 X Slope (%)

N/A

1.4

N/A







N/A

Ramp inside XWalk1?

Road Slope (%)

2.5 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 12.0 Curb Slope (%)

Ramp inside XWalk2?

Clear Space?