


Intersection ID: N/A	Main Street: HUNTER_CREST_LN	Cross Street: WOODLAWN_RD	Location:	SW
ADA ID: 535E9835C101	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 25

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance																																																																																																
	Possible Solutions:	<table><tr><th>Compliance</th><th>Description</th><th>Data</th><th>Compliance</th><th>Description</th><th>Data</th></tr><tr><td>N/A</td><td>Ramp Length (in)</td><td>47.0</td><td>Yes</td><td>Ramp Slope (%)</td><td>5.7</td></tr><tr><td>Yes</td><td>Ramp Width (in)</td><td>49.0</td><td>No</td><td>Ramp XSlope (%)</td><td>7.1</td></tr><tr><td>N/A</td><td>Flare Type LT</td><td>N/A</td><td>N/A</td><td>Flare Type RT</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Slope LT (%)</td><td>N/A</td><td>N/A</td><td>Flare Slope RT (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Flare Traversable LT?</td><td>N/A</td><td>N/A</td><td>Flare Traversable RT?</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing Length (in)</td><td>N/A</td><td>N/A</td><td>DWS Provided?</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing Width (in)</td><td>N/A</td><td>N/A</td><td>DWS Contrast?</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing Slope (%)</td><td>N/A</td><td>N/A</td><td>DWS Length (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Landing X Slope (%)</td><td>N/A</td><td>N/A</td><td>DWS Full Width?</td><td>N/A</td></tr></table>						Compliance	Description	Data	Compliance	Description	Data	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	5.7	Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	7.1	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A																															
	Compliance	Description	Data	Compliance	Description	Data																																																																																												
	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	5.7																																																																																												
	Yes	Ramp Width (in)	49.0	No	Ramp XSlope (%)	7.1																																																																																												
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A																																																																																												
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A																																																																																												
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A																																																																																												
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A																																																																																												
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A																																																																																												
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A																																																																																												
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A																																																																																													
Surveyor Notes:	<table><tr><td>N/A</td><td>N/A</td><td>DWS Offset (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Shared Landing?</td><td>N/A</td><td></td></tr><tr><td>N/A</td><td>Gutter Ponding?</td><td>N/A</td><td>N/A</td><td>Gutter Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Gutter Lip Ht (in)</td><td>N/A</td><td>N/A</td><td>Gutter X Slope (%)</td><td>N/A</td></tr><tr><td>N/A</td><td>Painted X Walk1?</td><td>No</td><td>N/A</td><td>Painted X Walk2?</td><td>No</td></tr><tr><td></td><td>X Walk 1 Direction</td><td>To E</td><td></td><td>X Walk 2 Direction</td><td>To N</td></tr><tr><td>N/A</td><td>X Walk 1 Width (in)</td><td>N/A</td><td>N/A</td><td>X Walk 2 Width (in)</td><td>N/A</td></tr><tr><td></td><td>X Walk 1 Slope (%)</td><td>1.2</td><td></td><td>X Walk 2 Slope (%)</td><td>7.9</td></tr><tr><td></td><td>X Walk 1 X Slope (%)</td><td>5.9</td><td></td><td>X Walk 2 X Slope (%)</td><td>2.9</td></tr><tr><td>N/A</td><td>Ramp inside XWalk1?</td><td>N/A</td><td>N/A</td><td>Ramp inside XWalk2?</td><td>N/A</td></tr><tr><td></td><td>Road Slope (%)</td><td>6.2</td><td>N/A</td><td>Clear Space?</td><td>N/A</td></tr><tr><td></td><td>Road X Slope (%)</td><td>4.3</td><td>N/A</td><td>Clear Space to XWalk (in)</td><td>N/A</td></tr><tr><td>N/A</td><td>Any Obstructions?</td><td>N/A</td><td>N/A</td><td>Storm Grate/Utility Hazard?</td><td>N/A</td></tr><tr><td></td><td>Obstruction Type</td><td></td><td></td><td>Storm Grate/Utility Type</td><td></td></tr><tr><td></td><td></td><td>N/A</td><td></td><td></td><td>N/A</td></tr><tr><td></td><td></td><td></td><td>Yes</td><td>Surface Condition? (G/P)</td><td>Good</td></tr></table>						N/A	N/A	DWS Offset (in)	N/A	N/A	Shared Landing?	N/A		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No		X Walk 1 Direction	To E		X Walk 2 Direction	To N	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	7.9		X Walk 1 X Slope (%)	5.9		X Walk 2 X Slope (%)	2.9	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		Road Slope (%)	6.2	N/A	Clear Space?	N/A		Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		Obstruction Type			Storm Grate/Utility Type				N/A			N/A				Yes	Surface Condition? (G/P)	Good
N/A	N/A	DWS Offset (in)	N/A																																																																																															
N/A	Shared Landing?	N/A																																																																																																
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A																																																																																													
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A																																																																																													
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No																																																																																													
	X Walk 1 Direction	To E		X Walk 2 Direction	To N																																																																																													
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A																																																																																													
	X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	7.9																																																																																													
	X Walk 1 X Slope (%)	5.9		X Walk 2 X Slope (%)	2.9																																																																																													
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A																																																																																													
	Road Slope (%)	6.2	N/A	Clear Space?	N/A																																																																																													
	Road X Slope (%)	4.3	N/A	Clear Space to XWalk (in)	N/A																																																																																													
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A																																																																																													
	Obstruction Type			Storm Grate/Utility Type																																																																																														
		N/A			N/A																																																																																													
			Yes	Surface Condition? (G/P)	Good																																																																																													
PROW/ADA:	Not Found, R304.5.3																																																																																																	
Street 1 Name	HUNTER CREST LN																																																																																																	
Stop Condition-Street 2	StopSign																																																																																																	
Street 2 Name	E WOODLAWN RD																																																																																																	
Stop Condition-Street 1	None																																																																																																	
Total Cost:	\$ 3200.00																																																																																																	

