


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 16088		Main Street: OXFORD_PL		Cross Street: QUEENS_RD		Location: NE							
ADA ID: 5360C2F0196D		Ramp Type: Directional1		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 1.25					
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance									
				Possible Solutions:		Compliance		Description		Data			
				Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	26.0		N/A	Grade Break?	N/A	
Surveyor Notes:				N/A		Yes	Ramp Width (in)	58.0		N/A	Grade Break Slope (%)	0.0	
						Yes	Ramp Slope (%)	2.2		N/A	Grade Break XSlope (%)	0.0	
PROW/ADA:				R304.5.3		No	Ramp XSlope (%)	2.6					
						N/A	Flare Type LT	N/A		N/A	Flare Type RT	N/A	
						N/A	Flare Slope LT (%)	N/A		N/A	Flare Slope RT (%)	0.0	
						N/A	Flare Traversable LT?	N/A		N/A	Flare Traversable RT?	N/A	
						N/A	Landing Length (in)	0.0		N/A	DWS Provided?	N/A	
						N/A	Landing Width (in)	0.0		N/A	DWS Contrast?	N/A	
						N/A	Landing Slope (%)	0.0		N/A	DWS Length (in)	N/A	
						N/A	Landing X Slope (%)	0.0		N/A	DWS Full Width?	N/A	
						N/A	Landing Curb? (Y/N)	N/A		N/A	DWS Offset LT (in)	N/A	
						N/A	Shared Landing?	N/A		N/A	DWS Offset RT (in)	N/A	
						N/A	Gutter Ponding?	0.0		N/A	Gutter Slope (%)	N/A	
						N/A	Gutter Lip Ht (in)	0.0		N/A	Gutter X Slope (%)	N/A	
						N/A	Painted X Walk1?	No			Road Slope (%)	3.8	
							X Walk 1 Direction	To S			Road X Slope (%)	1.6	
							X Walk 1 Width (in)	N/A			Clear Space?	N/A	
							X Walk 1 Slope (%)	3.8		N/A	Clear Space to XWalk (in)	N/A	
							X Walk 1 X Slope (%)	1.6		N/A	Storm Grate/Utility Hazard?	N/A	
						N/A	Ramp inside XWalk1?	N/A			Storm Grate/Utility Type		
						N/A	Any Obstructions?	N/A				N/A	
							Obstruction Type			Yes	Surface Condition? (G/P)	Good	
										N/A	Curb Slope (%)	9.2	
Total Cost:				\$	1600.00								

