


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|------------------------|---------------------|--------------------------------|------------------------|
| Intersection ID: 53374 | Main Street: PPC_DR | Cross Street: CRAVEN_THOMAS_RD | Location: NE |
| ADA ID: 53B7A736F7D2 | Ramp Type: Perp | Initial Pass/Fail: Fail | Overall Compliance: No |
| | | Severity Score: 25 | |

| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | |
|--|--|--|---|-----------------------------|-------------|-------------------|
|  | Possible Solutions: | | Compliance | Description | Data | Compliance |
| | Remove & Replace Entire Ramp. | | No | Ramp Length (in) | 71.0 | No |
| | | | Yes | Ramp Width (in) | 48.0 | No |
| | | | N/A | Flare Type LT | N/A | N/A |
| | | | N/A | Flare Slope LT (%) | N/A | N/A |
| | | | N/A | Flare Traversable LT? | N/A | N/A |
| | | | N/A | Landing Length (in) | N/A | N/A |
| | | | N/A | Landing Width (in) | N/A | N/A |
| | | | N/A | Landing Slope (%) | N/A | N/A |
| | | | N/A | Landing X Slope (%) | N/A | N/A |
| <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>R304.2.2, R304.5.3</p> | | | N/A | Flare Type RT | N/A | N/A |
| | | | N/A | Flare Slope RT (%) | N/A | N/A |
| | | | N/A | Flare Traversable RT? | N/A | N/A |
| | | | N/A | DWS Provided? | N/A | N/A |
| | | | N/A | DWS Contrast? | N/A | N/A |
| | | | N/A | DWS Length (in) | N/A | N/A |
| | | | N/A | DWS Full Width? | N/A | N/A |
| | | | N/A | DWS Offset (in) | N/A | N/A |
| | | | N/A | Gutter Ponding? | N/A | N/A |
| | | | N/A | Gutter Lip Ht (in) | N/A | N/A |
| <p>Total Cost:</p> <p>\$ 1850.00</p> | | | Yes | Painted X Walk1? | N/A | N/A |
| | | | To W | X Walk 1 Direction | N/A | N/A |
| | | | N/A | X Walk 1 Width (in) | 94.5 | N/A |
| | | | 0.4 | X Walk 1 Slope (%) | N/A | N/A |
| | | | 6.2 | X Walk 1 X Slope (%) | N/A | N/A |
| | | | N/A | Ramp inside XWalk1? | Yes | N/A |
| | | | N/A | Road Slope (%) | N/A | N/A |
| | | | N/A | Road X Slope (%) | N/A | N/A |
| | | | N/A | Any Obstructions? | N/A | N/A |
| | | | N/A | Obstruction Type | N/A | N/A |
| | | | N/A | Clear Space? | N/A | N/A |
| | | | N/A | Clear Space to XWalk (in) | N/A | N/A |
| | | | N/A | Storm Grate/Utility Hazard? | N/A | N/A |
| | | | N/A | Storm Grate/Utility Type | N/A | N/A |
| | | | Yes | Surface Condition? (G/P) | Good | Good |

