

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47974Main Street: TOM_SHORT_RDCross Street: BRYANT_FARMS_RDLocation: NWADA ID: 5424010F46B5Ramp Type: PerpInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name BRYANT FARMS RD
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

ossible Solutions:	<u>c</u>		
Remove & Replace Entire Ramp.			
	N		
	N		
	N		
	N		
	N		
urveyor Notes:	N		
N/A	N		
	N		
	N		
	N		
ROW/ADA:	N		
Not Found, R304.5.1, R304.2.2	N		
	N		
	N		

Total Cost: \$ 1850.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	94.0	No	Ramp Slope (%)	9.4		
No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	1.9		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		





