

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10041630Main Street:WHITEHALL\_PARK\_DRCross Street:N/ALocation:WADA ID: 5466B7AD0511Ramp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name ENTRANCE
Stop Condition-Street 2 StopSign
Street 2 Name WHITEHALL PARK DR
Stop Condition-Street 1 None

Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
R304.2.2, R304.5.3

Total Cost: \$ 3200.00







