

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10026312 Main Street: FAIRVIEW\_RD Cross Street: N/A Location: NW **Severity Score:** Ramp Type: Directional1 Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 54723E9273CC 1.25

Codes/Mitigation Info/Possible



Street 1 Name	ENTRANCE
Stop Condition-Street 1	StopSign
Street 2 Name	N/A
Stop Condition-Street 2	N/A

/Possible Solution			Field Measurements/Component Compliance						
Possible Solutions:			Compliance Description		Data	Comp	liance Description	Data	
Remove & Replace Entire Ramp.		).	N/A	Ramp Length (in)	90.0	N/A	Grade Break?	N/A	
·	•		Yes	Ramp Width (in)	59.5	N/A	Grade Break Slope (%)	0.0	
			Yes	Ramp Slope (%)	0.6	N/A	Grade Break XSlope (%)	0.0	
			No	Ramp XSlope (%)	2.8				
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No		Road Slope (%)	3.9	
				X Walk 1 Direction	То Е		Road X Slope (%)	2.9	
				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
				X Walk 1 Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A	
				X Walk 1 X Slope (%)	2.9	N/A	Storm Grate/Utility Hazard?	N/A	
			N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
			N/A	Any Obstructions?	N/A			N/A	
Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
					N/A	N/A	Curb Slope (%)	1.7	





