

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 6328	Main Street: E_W_T_HARRIS_RA	Cross Street: UNIVERSITY_CITY_BV	Location: SW
ADA ID: 55A0A0F974E7	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
Severity Score: 0.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	



Possible Solutions:

**Remove & Replace Entire Ramp.**

Surveyor Notes:

**N/A**

PROW/ADA:

**R304.5.3, R305.2**

Total Cost:

**\$ 1600.00**

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	24.0	Yes	Grade Break?	Yes
Yes	Ramp Width (in)	120.0	Yes	Grade Break Slope (%)	0.1
Yes	Ramp Slope (%)	2.7	No	Grade Break XSlope (%)	2.2
No	Ramp XSlope (%)	3.5			
Yes	Flare Type LT	N/A	Yes	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	164.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	119.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.1	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	0.1	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	No	DWS Offset LT (in)	138.0
N/A	Shared Landing?	No	No	DWS Offset RT (in)	10.0
Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	2.8
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.5
N/A	Painted X Walk1?	Yes		Road Slope (%)	5.0
	X Walk 1 Direction	To E		Road X Slope (%)	1.7
	X Walk 1 Width (in)	85.0		Clear Space?	Yes
	X Walk 1 Slope (%)	5.0	N/A	Clear Space to XWalk (in)	N/A
	X Walk 1 X Slope (%)	1.7	Yes	Storm Grate/Utility Hazard?	No
Yes	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
Yes	Any Obstructions?	No			N/A
	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	20.6

