

| | | | | | | | | | | | |
|--|--|---|--|---|--|------------------------|--|-----------------------------|--|-----|--|
| Intersection ID: 21994 | | Main Street: CREEKBED_LN | | Cross Street: PARK_RD | | Location: | | NW | | | |
| ADA ID: 55A2F1A56200 | | Ramp Type: PerpDiag | | Initial Pass/Fail: Fail | | Overall Compliance: No | | Severity Score: 13.75 | | | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | | | |
|  | | <p>Possible Solutions:</p> <p>Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.</p> <p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R304.2.2, R304.5.3</p> | | Compliance | | Description | | Data | | | |
| | | | | N/A | | Ramp Length (in) | | 60.0 | | No | |
| | | | | Yes | | Ramp Width (in) | | 48.0 | | No | |
| | | | | N/A | | Flare Type LT | | N/A | | N/A | |
| | | | | N/A | | Flare Slope LT (%) | | N/A | | N/A | |
| | | | | N/A | | Flare Traversable LT? | | N/A | | N/A | |
| | | | | N/A | | Landing Length (in) | | N/A | | N/A | |
| | | | | N/A | | Landing Width (in) | | N/A | | N/A | |
| | | | | N/A | | Landing Slope (%) | | N/A | | N/A | |
| | | | | N/A | | Landing X Slope (%) | | N/A | | N/A | |
| N/A | | Landing Curb? (Y/N) | | N/A | | N/A | | N/A | | | |
| N/A | | Shared Landing? | | N/A | | | | | | | |
| N/A | | Gutter Ponding? | | N/A | | N/A | | Gutter Slope (%) | | | |
| N/A | | Gutter Lip Ht (in) | | N/A | | N/A | | Gutter X Slope (%) | | | |
| N/A | | Painted X Walk1? | | No | | N/A | | Painted X Walk2? | | | |
| | | X Walk 1 Direction | | To S | | | | X Walk 2 Direction | | | |
| N/A | | X Walk 1 Width (in) | | N/A | | N/A | | X Walk 2 Width (in) | | | |
| | | X Walk 1 Slope (%) | | 4.4 | | | | X Walk 2 Slope (%) | | | |
| | | X Walk 1 X Slope (%) | | 3.7 | | | | X Walk 2 X Slope (%) | | | |
| N/A | | Ramp inside XWalk1? | | N/A | | N/A | | Ramp inside XWalk2? | | | |
| | | Road Slope (%) | | 0.9 | | N/A | | Clear Space? | | | |
| | | Road X Slope (%) | | 5.5 | | N/A | | Clear Space to XWalk (in) | | | |
| N/A | | Any Obstructions? | | N/A | | N/A | | Storm Grate/Utility Hazard? | | | |
| | | Obstruction Type | | | | | | Storm Grate/Utility Type | | | |
| | | | | | | N/A | | N/A | | | |
| | | | | | | Yes | | Surface Condition? (G/P) | | | |
| | | | | | | | | Good | | | |

