

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

5.3

0.3

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

**Cross Street: ARDREY KELL RD** Intersection ID: 28291 Main Street: COMMUNITY HOUSE RD Location: SE **Overall Compliance: No** ADA ID: 55FC5C27EA3B Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 8.75

**Codes/Mitigation Info/Possible Solution** 

## **Field Measurements/Component Compliance**

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Flare Type RT

Data

105.0

47.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Flare Traversable LT?



**COMMUNITY HOUSE RD** Street 1 Name Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions: Complia	
Remove & Replace Entire Ramp. N/A	Ramp Length (in)
 No	Ramp Width (in)
N/A	Flare Type LT
N/A	Flare Slope LT (%)
N/A	Flare Traversable LT
N/A	Landing Length (in)
Surveyor Notes: N/A	Landing Width (in)
N/A N/A	Landing Slope (%)
N/A	Landing X Slope (%
N/A	Landing Curb? (Y/N
N/A	Shared Landing?
PROW/ADA: N/A	Gutter Ponding?
Not Found, R304.5.1	Gutter Lip Ht (in)
, N/A	Painted X Walk1?
	X Walk 1 Direction
N/A	X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (%
N/A	Ramp inside XWalk

			N/A
PROW/ADA:			N/A
Not Found,	R304.5.1		N/A
			N/A
Total Cost:		\$ 1850.00	

\$	1850.00	Obstruction Ty
		1
A		





