


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10027726	Main Street: GRIFFITH_RD	Cross Street: N/A	Location: NW
ADA ID: 564B3728A81A	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 33.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	32.0	No
			No	Ramp Width (in)	47.0	No
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A
			N/A	Shared Landing?	N/A	
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
			N/A	Painted X Walk1?	No	N/A
				X Walk 1 Direction	To SE	X Walk 2 Direction
			N/A	X Walk 1 Width (in)	N/A	N/A
				X Walk 1 Slope (%)	4.3	X Walk 2 Slope (%)
				X Walk 1 X Slope (%)	3.5	X Walk 2 X Slope (%)
			N/A	Ramp inside XWalk1?	N/A	N/A
				Road Slope (%)	5.5	N/A
				Road X Slope (%)	2.4	N/A
			N/A	Any Obstructions?	N/A	N/A
				Obstruction Type		Storm Grate/Utility Hazard?
						Storm Grate/Utility Type
					N/A	N/A
					Yes	Surface Condition? (G/P)
						Good

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Street 1 Name **GRIFFITH RD**
 Stop Condition-Street 2 **None**
 Street 2 Name **ENTRANCE**
 Stop Condition-Street 1 **None**

