

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Good

Surface Condition? (G/P)

Intersection ID: 9869Main Street: OAKLAWN_AVCross Street: RUSH_WIND_DRLocation: NWADA ID: 564BFE43FFD6Ramp Type: PerpDiagInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 50

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

OAKLAWN AV None RUSH WIND DR StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

r leid Measurements/Component Compnance				
liance Description	Data	Comp	oliance Description	Data
Ramp Length (in)	61.0	No	Ramp Slope (%)	12.6
Ramp Width (in)	48.0	No	Ramp XSlope (%)	7.7
Flare Type LT	N/A	N/A	Flare Type RT	N/A
Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	1.5	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	No
X Walk 1 Direction	To S		X Walk 2 Direction	To SE
X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	4.1
X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	0.2
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	3.0	N/A	Clear Space?	N/A
Road X Slope (%)	4.4	N/A	Clear Space to XWalk (in)	N/A
Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
Obstruction Type			Storm Grate/Utility Type	
	Ramp Length (in) Ramp Width (in) Flare Type LT Flare Slope LT (%) Flare Traversable LT? Landing Length (in) Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? Gutter Ponding? Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) Road X Slope (%) Any Obstructions?	Iliance Description Data Ramp Length (in) 61.0 Ramp Width (in) 48.0 Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) 1.5 Painted X Walk1? No X Walk 1 Direction To S X Walk 1 Width (in) N/A X Walk 1 Slope (%) 3.2 Ramp inside XWalk1? N/A Road Slope (%) 3.0 Road X Slope (%) 4.4 Any Obstructions? N/A	Isliance Description Data Composition Ramp Length (in) 61.0 No Ramp Width (in) 48.0 No Flare Type LT N/A N/A Flare Slope LT (%) N/A N/A Flare Traversable LT? N/A N/A Landing Length (in) N/A N/A Landing Width (in) N/A N/A Landing Slope (%) N/A N/A Landing Slope (%) N/A N/A Landing Curb? (Y/N) N/A N/A Shared Landing? N/A N/A Gutter Ponding? N/A N/A Gutter Lip Ht (in) 1.5 N/A N/A N/A N/A X Walk 1 Direction To S X Walk 1 Width (in) N/A N/A X Walk 1 Slope (%) 3.2 Ramp inside XWalk1? N/A N/A Road Slope (%) 3.0 N/A Road X Slope (%) 4.4 N/A Any Obstructions?	Ramp Length (in) Ramp Width (in) Flare Type LT Flare Slope LT(%) No Ramp Width (in) No Ramp Width (in) Flare Traversable LT? Landing Length (in) No Ramp Width (in) No Ramp XSlope (%) No No Ramp XSlope (%) No Ramp XSlope (%) No No Ramp XSlope RT No No No No Ramp Traversable RT? No No No No Router Traversable RT? No





