

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

11.1

6.5

N/A

Good

Intersection ID: 42456 Main Street: SUNNINGHILL PARK RD Cross Street: KINGSLEY VIEW DR Location: SW **Overall Compliance: No** ADA ID: 56937540ABB4 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

No

No

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Flare Traversable RT?

Flare Type RT

Data

158.0

45.0

N/A


No

N/A

2.7

5.2

To SE



KINGSLEY VIEW DR Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Compliance Description
Remove & Replace Entire Ramp.	N/A Ramp Length (in)
·	No Ramp Width (in)
	N/A Flare Type LT
	N/A Flare Slope LT (%)
	N/A Flare Traversable L
	N/A Landing Length (in)
Surveyor Notes:	N/A Landing Width (in)
N/A	N/A Landing Slope (%)
	N/A Landing X Slope (%
	N/A Landing Curb? (Y/N
	N/A Shared Landing?
PROW/ADA:	N/A Gutter Ponding?
Not Found, R304.5.1, R304.2.2,	N/A Gutter Lip Ht (in)
R304.5.3	N/A Painted X Walk1?
	X Walk 1 Direction
	N/A X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (
	N/A Pamp inside YWalk

The state of the s	AL MINE TO
A STATE OF THE PARTY OF THE PAR	The state of the s
	Contract of the Contract of th

Total Cost:







X Walk 1 X Slope (%)

Flare Traversable LT?