

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.4

4.5

N/A

Good

Intersection ID: 12587 Main Street: CAMP GREENE ST **Cross Street: WILKINSON BV** Location: NW **Overall Compliance: No ADA ID: 56A1F2BC3B58** Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

60.5

48.0

N/A

No

To E

N/A

2.5

4.6

N/A

N/A

N/A

N/A

N/A

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?



CAMP GREENE ST Street 1 Name Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A

Possible Solutions:	Comp	liance	Description
Remove & Replace Entire Ramp.	N/A	Ram	p Length (in)
·	Yes	Ram	p Width (in)
	N/A	Flare Type LT Flare Slope LT (%)	
	N/A		
	N/A	Flare	Traversable L
	N/A	Land	ing Length (in)
Surveyor Notes:	N/A	Land	ing Width (in)
N/A	N/A	Land	ing Slope (%)
	N/A	Land	ing X Slope (%
	N/A	Land	ing Curb? (Y/N
	N/A	Share	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.2.2, R304.5.3	N/A	Gutte	er Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	ılk 1 Width (in)
		X Wa	ılk 1 Slope (%)
		X Wa	ılk 1 X Slope (%
	N/A	Ram	p inside XWalk
		Road	Slope (%)
		Road	X Slope (%)

510	JP

Total Cost:



N/A

1850.00

