

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30018 Main Street: W\_MALLARD\_CREEK\_CHURCIC\_RSDs Street: BERKELEY\_PLACE\_DR Location: NE

ADA ID: 56DA79925935 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25

## Codes/Mitigation Info/Possible Solution



Street 1 Name MALLARD CREEK CHURCH RD
Stop Condition-Street 2 Signal
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:	<u> </u>
Remove & Replace Entire Ramp.	N
	Y
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
R304.2.2, R304.5.3	N
	N
	N

Total Cost:	\$ 1850.00

Field Measurements/Component Compliance						
Compli	iance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	85.0	No	Ramp Slope (%)	12.1	
Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.8	
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	113.0	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	





