

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 8246 Main Street: AU		reet: AUGUSTA_ST	Cross Street: CATHERINE_SIMMONS_AV				Location:	NE		
ADA ID: 57063CEA67	A ID: 57063CEA674A Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Alera - Part		Possible Solutions:		Compliance Description			Data Compliance Description			
The second s		Remove & Replace Curb Ramp W Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	39.0	No	Ramp Slope (%)	9.0	
			-	Yes	Ramp Width (in)	104.0	Yes	Ramp XSlope (%)	1.2	
a Print and a				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		4		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	and the second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	ATHERINE SIMMONS AV	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		-		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	the second second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
a de	11 mars	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
18-5	A PARA BUILD	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	A Contract The state			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
				X Walk 1 Direction	To S		X Walk 2 Direction	To E		
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	AUGUSTA ST				X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	0.5	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	0.8	
Street 2 Name	CATHERINE SIMMONS AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	None				Road Slope (%)	0.4	N/A	Clear Space?	N/A	
					Road X Slope (%)	2.5	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

