cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10026423 Main Street: FARMBROOK DR Cross Street: N/A								Location:	S
Intersection ID: 10026423	Main Street: FARMBROOK_DR								
ADA ID: 575152E260F6	F6 Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A FRANK AND A STATE OF	Poss	Possible Solutions:		Compliance Description Data			Compliance Description		Data
the state of	Re	emove & Replace Curb Ran	np With	N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	3.2
	Tw	vo New Directional Ramps	or	No	Ramp Width (in)	41.0	Yes	BlendTrans XSlope (%)	1.5
	Eq.	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
C	(7 A A A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
87 b.	A A A A A			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
States and a state of the state	Surve	eyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Α		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A			
Theres	PRO	W/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	No	ot Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
· / Barbara	1. 1. 1			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	N/A				X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	0.3
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	0.1
Street 2 Name FA	ARMBROOK DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	1.1		Clear Space?	N/A
					Road X Slope (%)	2.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total	l Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.1