

Access Compliance Report Public Rights-of-Way (Curb Ramps)




Intersection ID: 10027410 Main Street: GOLF_ACRES_DR Cross Street: N/A Location: N

ADA ID: 57ABB24D5043 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name ENTRANCE
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

No
N/A
N/A
N/A
Surveyor Notes:

N/A
N/A

N/A

PROW/ADA:

R304.5.1, R304.5.3

N/A

N/A

N/A

Total Cost: \$ 1850.00

Comp	liance Description	Data	Comp	liance Descript	ion	Data
N/A	Ramp Length (in)	46.5	Yes	Ramp Slope (%	o)	5.2
No	Ramp Width (in)	40.0	No	Ramp XSlope (%)	7.0
N/A	Flare Type LT	N/A	N/A	Flare Type RT		N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT	(%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversal	ole RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided	?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	•	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in	٦)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width	1?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%	6)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope	(%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk	2?	N/A
	X Walk 1 Direction	To SW		X Walk 2 Direct	tion	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width	(in)	N/A
	X Walk 1 Slope (%)	0.5		X Walk 2 Slope	(%)	N/A
	X Walk 1 X Slope (%)	2.6		X Walk 2 X Slo	pe (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside X\	Nalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?		N/A
	Road X Slope (%)	N/A	N/A	Clear Space to	XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Ut	ility Hazard?	N/A
	Obstruction Type			Storm Grate/Ut	ility Type	
		N/A				N/A

Surface Condition? (G/P)

Good





