

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



			`		. /							
Intersection ID: N/A	Main Street: STEELE_CREEK_RD				Cross Street: ASHEFORD_WOODS_LN				Location:	SW		
ADA ID: 5801C2BC142F	Ramp Ty	Ramp Type: Combination1				ail: Fail Overall	nce: N	o Severity Score:	10			
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description		Data Compliance Description			Data		
Mar all		Remove & Replace E	ntire Rai	mp.	N/A	Ramp Length LT (in)	53.3	N/A	Ramp Length RT (in)	52.0		
al and	Nea X				Yes	Ramp Width LT (in)	49.0	No	Ramp Width RT (in)	46.5		
					Yes	Ramp Slope LT (%)	6.8	Yes	Ramp Slope RT (%)	0.5		
ELABORE I					No	Ramp XSlope LT (%)	2.6	No	Ramp XSlope RT (%)	2.1		
EX CE					N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	7.7		
				Yes	Ramp Width (in)	59.0	No	Ramp XSlope (%)	3.2			
ASHEFORD WOODS LN		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
	S AN A A	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
	g Martin				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
the contention	E Sa Ma				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
	<b>10</b>				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	L BOR MAY	Not Found, R304.5.1, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
	· · · · · · · · · · · · · · · · · · ·			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A			
	化 的第一十三				N/A	Shared Landing?	N/A					
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
Stop Condition-Street 1 AS	SHEFORD WOODS LN				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
Street 2 Name	N/A					X Walk 1 Direction	To N		X Walk 2 Direction	N/A		
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A		
						X Walk 1 Slope (%)	3.1		X Walk 2 Slope (%)	N/A		
						X Walk 1 X Slope (%)	5.2		X Walk 2 X Slope (%)	N/A		
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
						Road Slope (%)	N/A		Clear Space?	N/A		
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
				1. 11 11				N/A	Any Obstruction?	N/A		
				10	Sant Sant	20mm			Obstruction Type			

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A

N/A

 Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 7.8





