

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



				-					
Intersection ID: 13912	Main Street: E_STONEWALL_ST			Street:	CHARLOTTETOWNE	Location:	NE		
ADA ID: 582181B7F6A	7F6AF Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace Entire Ramp	).	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	8.9
				Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.4
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the second	The start water			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	- AND STATES			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	in the second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
157 0		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the the the	t. STETOWNE AV	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	CHARLOU US	1		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
d. Kon	X- In			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
A RRA	a har Frid	1		N/A	Shared Landing?	N/A			
A JOIN BEAM	the state	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Later 1		Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the second secon		·····		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
e.	1 1 al Mar				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	118.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CHARLOTTETOWNE AV	_			X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	2.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

