

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13916 Main Street: CLANTON_RD **Cross Street: WEST BV** Location: NE ADA ID: 584C58AAF911 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 25

Codes/Mitigation Info/Possible Solution



Street 1 Name **DONALD ROSS RD** Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Restripe Crosswalk. Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3

Total Cost: 2050.00

Field Measurements/Component Compliance						
Compl	iance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	60.0	No	Ram	Slope (%)	9.0
Yes	Ramp Width (in)	48.0	No	Ram	XSlope (%)	5.8
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)		N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?		N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	Yes	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To W		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	124.0	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.1		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.2		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	No	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





