## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10041619 Main Street: WHITEHALL_COMMONS_CENTERSISEStreet: N/A								Location:	NW
ADA ID: 587A65618BE5					ail: Fail Overall (				
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A A A A A A A A		Possible Solutions:							Data
× 1 1 1 . *	× CAN / BE	Remove & Replace Curb Ra	np With	N/A	Ramp Length (in)	39.0	Yes	Ramp Slope (%)	5.7
	- Skiel	Two New Directional Ramps	•	No	Ramp Width (in)	42.5	Yes	Ramp XSlope (%)	0.7
		Equivalent.	•	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	All all			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
THE				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
and the second second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
and the second second				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name HALL COMMO	ONS CENTER DR	-			X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	1.5
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	1.3
Street 2 Name	ENTRANCE			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	0.7	N/A	Clear Space?	N/A
					Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

