

Intersection ID: 28237		Main Street: HIGHGROVE_ST		Cross Street: SOCIETY_ST		Location:		NW	
ADA ID: 58BB3C1F6357		Ramp Type: PerpDiag		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 33.75	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
<div><div><p>Aerial photograph of the intersection of Society St and Highgrove St. The streets are labeled in yellow. Blue wheelchair icons indicate accessible curb ramp locations at all four corners.</p></div><div><p>Possible Solutions: <b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b></p><p>Surveyor Notes: <b>N/A</b></p><p>PROW/ADA: <b>Not Found, R304.5.1, R304.2.2</b></p></div></div>				Compliance	Description	Data	Compliance	Description	Data
				N/A	Ramp Length (in)	93.0	No	Ramp Slope (%)	13.9
				No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	1.6
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	2.3
					X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	0.3
				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	1.6	N/A	Clear Space?	N/A
					Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A				
Total Cost: \$ 3200.00					Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
						Yes	Surface Condition? (G/P)	Good	

