


Intersection ID: 10032240	Main Street: MOSS_RD	Cross Street: N/A	Location:	W
ADA ID: 58E8B746836E	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 12.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance										
	Possible Solutions:					Compliance			Description			Data	
	Remove & Replace Entire Ramp.					N/A			Ramp Length (in)			120.0	
						Yes			Ramp Width (in)			48.0	
						N/A			Flare Type LT			N/A	
						N/A			Flare Slope LT (%)			N/A	
						N/A			Flare Traversable LT?			N/A	
						N/A			Landing Length (in)			N/A	
						N/A			Landing Width (in)			N/A	
						N/A			Landing Slope (%)			N/A	
						N/A			Landing X Slope (%)			N/A	
Surveyor Notes:													
N/A													
PROW/ADA:													
R304.5.3													
Street 1 Name		MOSS RD											
Stop Condition-Street 2		None											
Street 2 Name		N/A											
Stop Condition-Street 1		N/A											
Total Cost:		\$ 1850.00											

