cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 5954	Main Street: PARSIFAL_LN	Cross S	Cross Street: ATKINS_RIDGE_DR				Location:	NE
ADA ID: 5904DBE34B68	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance			ice: No		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description Data			Compliance Description Data		Data
	Remove & Replace Curb Ram	o With	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	5.2
	Two New Directional Ramps o		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	5.9
	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Sec. 1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Part -		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	1		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ATTAINS RIDGE DO	St. F		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
d. The			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.5.3	}	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	·····,····,····,····,····,····,····,····		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
all and a second s	and the second			X Walk 1 Direction	To SW		X Walk 2 Direction	To NW
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name ATKINS I	RIDGE DR			X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	2.8
Stop Condition-Street 2	None			X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	5.8
Street 2 Name PAR	RSIFAL LN		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None			Road Slope (%)	4.0	N/A	Clear Space?	N/A
				Road X Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P) Good

