

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

40.0

56.0

0.4

0.3

3.0

4.3

N/A

N/A

N/A

Good

11.8

Intersection ID: 45882 Main Street: HOMESTEAD_GLEN_BV Cross Street: VALLEYDALE_RD Location: S

ADA ID: 591604FA62C5 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Compliance Description

N/A

Yes

No

Yes

N/A

Yes

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Type LT

Ramp XSlope LT (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

Yes

Yes

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Ramp XSlope RT (%)

Data

61.0

54.0

9.2

1.5

48.5

N/A

49.0 No

N/A N/A



Street 1 Name

Stop Condition-Street 1

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RP & RT RP < 5%

PROW/ADA:

Not Found, R304.5.3, R304.3.2





Total Cost:



1800.00

N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
				Obstruction Type	
	**************************************				N/A
			N/A	Storm Grate/Utility Hazard?	N/A
			l	Storm Grate/Utility Type	

Yes

Surface Condition? (G/P)

Curb Slope (%)