


# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

Intersection ID: 10033044	Main Street: NOLLEY_CT	Cross Street: N/A	Location: E
ADA ID: 59266FED866E	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 21.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		<b>Compliance</b>	<b>Description</b>	<b>Data</b>	
	<b>Remove &amp; Replace Curb Ramp With Two New Directional Ramps or Equivalent.</b>		N/A	Ramp Length (in)	71.0	<b>Yes</b>
			No	Ramp Width (in)	45.0	<b>No</b>
			N/A	Flare Type LT	N/A	<b>N/A</b>
			N/A	Flare Slope LT (%)	N/A	<b>N/A</b>
			N/A	Flare Traversable LT?	N/A	<b>N/A</b>
			N/A	Landing Length (in)	N/A	<b>N/A</b>
			N/A	Landing Width (in)	N/A	<b>N/A</b>
			N/A	Landing Slope (%)	N/A	<b>N/A</b>
			N/A	Landing X Slope (%)	N/A	<b>N/A</b>
<p>Surveyor Notes:</p> <p><b>N/A</b></p> <p>PROW/ADA:</p> <p><b>Not Found, R304.5.1, R304.5.3</b></p>			N/A	Flare Type RT	N/A	<b>N/A</b>
			N/A	Flare Slope RT (%)	N/A	<b>N/A</b>
			N/A	Flare Traversable RT?	N/A	<b>N/A</b>
			N/A	DWS Provided?	N/A	<b>N/A</b>
			N/A	DWS Contrast?	N/A	<b>N/A</b>
			N/A	DWS Length (in)	N/A	<b>N/A</b>
			N/A	DWS Full Width?	N/A	<b>N/A</b>
			N/A	DWS Offset (in)	N/A	<b>N/A</b>
			N/A	Gutter Ponding?	N/A	<b>N/A</b>
			N/A	Gutter Lip Ht (in)	N/A	<b>N/A</b>
			N/A	Painted X Walk1?	No	<b>N/A</b>
				X Walk 1 Direction	To NW	
				X Walk 1 Width (in)	N/A	
				X Walk 1 Slope (%)	2.3	
				X Walk 1 X Slope (%)	1.7	
			N/A	Ramp inside XWalk1?	N/A	<b>N/A</b>
				Road Slope (%)	2.3	
				Road X Slope (%)	4.1	<b>N/A</b>
			N/A	Any Obstructions?	N/A	<b>N/A</b>
				Obstruction Type		
Total Cost: \$ 3200.00						
			N/A			<b>N/A</b>
			<b>Yes</b>	Surface Condition? (G/P)		<b>Good</b>
			<b>No</b>	Curb Slope (%)		<b>12.1</b>

