

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29370	Main Street: SAM_WILSON_RD			Street:	WILSON_GLEN_DR	Location:	NE			
ADA ID: 599B90800AD6	6 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	The second second	Possible Solutions:					a Compliance Description Data			
	all a	Remove & Replace Entire Ramp).	N/A	Ramp Length (in)	46.0	No	Ramp Slope (%)	8.8	
The second second	9		-	No	Ramp Width (in)	40.0	Yes	Ramp XSlope (%)	0.0	
	Vine			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	Marcall .			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	Set The			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	10. Jest	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
WILSON	GLEN DR			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	In the second			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A					
T. Roll	San trille	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
A P F	R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
F			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
A CONTRACTOR OF					X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
A COMPANY			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name WIL	SON GLEN DR	-			X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	2.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

