cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6103	D: 6103 Main Street: GRENELEFE_VILLAGE_RD				Cross Street: PERIWINKLE_CT				NE
ADA ID: 59AF64D44151	ID: 59AF64D44151 Ramp Type: Perp				Initial Pass/Fail: Fail Overall Compliance: No				13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	Sec.	Possible Solutions:					Data Compliance Description		Data
		Remove & Replace Entire R	Ramp.	N/A	Ramp Length (in)	24.0	No	Ramp Slope (%)	10.5
	1.			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.4
to a loss of the second				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	1	1		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	ACE -			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	a Sure			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Mana	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
En enter		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
the second second	A HALAN			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A CARE LA	MARK Y			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	LAN ak			N/A	Shared Landing?	N/A			
2 De 10		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Strain Strain	Not Found, R304.2.2, R304.	5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	I that	,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To W		X Walk 2 Direction	N/A
and the second second	and the second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PERIWINKLE CT	-			X Walk 1 Slope (%)	1.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1850.	.00	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

