

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 9622	Main Street: FAIRFIELD_ST	Cross Street: N/A	Location: SW
ADA ID: 5A240DF8EF8E	Ramp Type: Directional1	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 7.75	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	81.0	Yes
	Remove & Replace Gutter.		Yes	Ramp Width (in)	59.0	Yes
			Yes	Ramp Slope (%)	1.1	No
			No	Ramp XSlope (%)	3.2	
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			Yes	Landing Length (in)	70.5	Yes
			Yes	Landing Width (in)	62.0	Yes
Surveyor Notes: N/A			Yes	Landing Slope (%)	1.9	Yes
			No	Landing X Slope (%)	2.2	No
			N/A	Landing Curb? (Y/N)	No	Yes
			N/A	Shared Landing?	Yes	Yes
			Yes	Gutter Ponding?	No	No
			Yes	Gutter Lip Ht (in)	0.0	No
			N/A	Painted X Walk1?	No	
				X Walk 1 Direction	To N	
				X Walk 1 Width (in)	N/A	
				X Walk 1 Slope (%)	3.6	N/A
PROW/ADA: R304.5.3, R305.1.4, R304.5.4				X Walk 1 X Slope (%)	2.3	Yes
			N/A	Ramp inside XWalk1?	N/A	
			Yes	Any Obstructions?	No	
				Obstruction Type		
			Yes	Surface Condition? (G/P)		Good
			N/A	Curb Slope (%)		12.0
Total Cost:		\$ 2350.00				

