

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7169 Main Street: MILBURN_CT Cross Street: TILDEN_RD Location: N **Overall Compliance: No** ADA ID: 5A2D896F81A4 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 8.75

Codes/Mitigation Info/Possible Solution



MILBURN CT Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A N/A Stop Condition-Street 1

Possible Solutions:	C			
Remove & Replace Entire Ramp.				
·	No			
	N/			
Surveyor Notes:	N/			
N/A	N/			
	N/			
	N/			
	N/			
PROW/ADA:	N/			
Not Found, R304.5.1	N/			
	N/			
	N/			

Total Cost: 1850.00

Field Measurements/Component Compliance								
Compl	iance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	48.0	Yes	Ram	Slope (%)	7.8		
No	Ramp Width (in)	36.0	Yes	Ram	XSlope (%)	0.9		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A		
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	ılk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.4		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.2		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		





