cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interpection ID: N/A	Intersection ID: N/A Main Street: COPPER WY Cross Street: CHUCK HOLLOW LN Location:								
Intersection ID: N/A	Main Str	Main Street: COPPER_WY			Cross Street: CHUCK_HOLLOW_LN				NW
ADA ID: 5A52C51404E7	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	E E	Possible Solutions:		Compliance Description D			Comp	Data	
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	105.0	No	Ramp Slope (%)	10.9
		Two New Directional Ramps or	•	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.8
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
The state of the second				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A. M				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
And Alexand		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
Cillian 🛵		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
	Martin Contraction of the	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
19-7-18 0		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		· ·		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				N/A	X Walk 1 Width (in)	56.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	CHUCK HOLLOW LN				X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	0.6
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.7		X Walk 2 X Slope (%)	1.2
Street 2 Name	COPPER WY			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.7	N/A	Clear Space?	N/A
					Road X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

