cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: PENCE_GROVE_RD Cross Street: PENCE_RD								Location:	NW
ADA ID: 5A9CC7A1AD30	5A9CC7A1AD30 Ramp Type: Combination1Diag			Initial Pass/Fail: Fail Overall Complian			ce: No Severity Score:		0
Co	odes/Mitigation Info	/Possible Solution			Field Measure	ments/Co	ompo	nent Compliance	
		Possible Solutions:		Comp	liance Description	Data	Compliance Description		Data
	60 / 1 / 1	Remove & Replace Curb Ra	amp With	N/A	Ramp Length LT (in)	47.0	N/A	Ramp Length RT (in)	47.0
		Two New Directional Ramps			Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	60.0
the second second		Equivalent.		Yes	Ramp Slope LT (%)	5.7	Yes	Ramp Slope RT (%)	5.6
				Yes	Ramp XSlope LT (%)	0.4	Yes	Ramp XSlope RT (%)	1.2
				N/A	Ramp Length (in)	50.0	Yes	Ramp Slope (%)	5.9
States States				No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	0.1
and the state of the state of		Surveyor Notes:		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
<u> </u>	5	N/A		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	1 1.3			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
LEDNER				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E.				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	6.	PROW/ADA:		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
14	an -	Not Found, R304.5.1		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	1 - 21			N/A	Shared Landing?	N/A			
	1. 30			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Street 1 Name	None	-		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1	PENCE RD			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	StopSign				X Walk 1 Direction	To S		X Walk 2 Direction	To E
Stop Condition-Street 2	PENCE GROVE RD				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	0.1
					X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	1.0
		Total Cost: \$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)	0.9		Clear Space?	N/A
					Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
							N/A	Any Obstruction?	N/A
			The second secon					Obstruction Type	
			-	11	and the second s				N/A
							N/A	Storm Grate/Utility Hazard?	N/A
			and the second	/				Storm Grate/Utility Type	IV/A

 Storm Grate/Utility Type
 N/A

 Yes
 Surface Condition? (G/P)
 Good

 Curb Slope (%)
 18.5





