

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: C000				Leastion	-					
Intersection ID: 6889				Cross Street: PLUMSTEAD_RD				Location:	E	
ADA ID: 5AB4BF758EDB	DA ID: 5AB4BF758EDB Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance:			nce: N	o Severity Score:	25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			ata Compliance Description		Data	
	Mallink park	Remove & Replace Entire Ramp		N/A	Ramp Length (in)	43.5	No	Ramp Slope (%)	14.0	
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	1			Yes	Ramp Width (in)	79.0	Yes	Ramp XSlope (%)	1.8	
	AND A STOL			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	1 Martin Martin			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	GROVE_RD			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	and the second	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
6	1 11/2			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	And Real Property in			N/A	Shared Landing?	N/A				
	15	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	MA -	R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
The Assessment				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
2 3				X Walk 1 Direction	To W		X Walk 2 Direction	N/A		
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	PLUMSTEAD DR				X Walk 1 Slope (%)	4.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	