

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

64.0

49.0

8.8

2.8

7.2

2.1

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 10023411 Main Street: CHOATE_CR Cross Street: N/A Location: W

ADA ID: 5AE0969AE54F Ramp Type: Combination2Diag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 0

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

Yes

No

No

N/A

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A N/A N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

Flare Traversable RT?

Data

58.0

49.0

N/A

N/A

17.0

48.0

N/A

N/A

N/A

N/A

N/A



Street 1 Name
Stop Condition-Street 1
CHOATE CR
Street 2 Name
StopSign
Stop Condition-Street 2
ENTRANCE

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.3.2





Total Cost:



3200.00

			_ : :	
Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	No
X Walk 1 Direction	To S		X Walk 2 Direction	То Е
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	2.3
X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	6.3
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	3.2		Clear Space?	N/A
Road X Slope (%)	4.0	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstruction?	N/A
			Obstruction Type	
				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
			Storm Grate/Utility Type	IVA
				N/A
		Yes	Surface Condition? (G/P)	Good
			Curb Slope (%)	17.0