cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



15.2

No

Curb Slope (%)

Intersection ID: 49315 Main Street: ANNA_JORDAN_DR Cross Street: ANNA_JORDAN_DR Location: SW								
Intersection ID: 49315 Main Str	Main Street: ANNA_JORDAN_DR			ross Street: ANNA_JORDAN_DR				SW
ADA ID: 5AECE56ADD8E Ramp Ty	Ramp Type: BlendTrans1 In			Fail Overall C	Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance Description			Data Compliance Description		
	Remove & Replace Curb Ramp W	Vith N/	A Rai	ımp Length (in)	48.0	Yes	BlendTrans Slope (%)	2.2
	Two New Directional Ramps or Equivalent.	Ye	s Rai	mp Width (in)	48.5	No	BlendTrans XSlope (%)	6.5
		N/.	A Fla	are Type LT	N/A	N/A	Flare Type RT	N/A
		N/.	A Fla	are Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/	A Fla	are Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/.	A Lar	nding Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/.	A Lar	nding Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/	A Lar	nding Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/	A Lar	nding X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/	A Lar	nding Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	4		A Sha	ared Landing?	N/A			
	PROW/ADA:	N/	A Gu	utter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.3	N/2	A Gu	ıtter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	·····, ····	N/	A Pai	inted X Walk1?	No	N/A	Painted X Walk2?	No
			ХV	Walk 1 Direction	To E		X Walk 2 Direction	To N
			ХV	Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name ROCKLAND DR	_		ХV	Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	6.2
Stop Condition-Street 1 None			ХV	Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	1.0
Street 2 Name ANNA JORDAN DR		N/	A Rai	mp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2 StopSign			Roa	ad Slope (%)	5.7		Clear Space?	N/A
			Roa	ad X Slope (%)	2.1	N/A	Clear Space to XWalk (in)	N/A
		N/.	A Any	y Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	00.00	Ob	struction Type			Storm Grate/Utility Type	
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good





