


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 15921	Main Street: LAWYERS_RD	Cross Street: CHESTNUT_LAKE_DR	Location: SE
ADA ID: 5B154F4E6A08	Ramp Type: ParaDiag	Initial Pass/Fail: Fail	Overall Compliance: No
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:		Compliance		Description		Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length LT (in)		53.0	N/A	Ramp Length RT (in)	50.5
<p>Surveyor Notes:</p> <p>RT RP < 5%</p> <p>PROW/ADA:</p> <p>R304.5.3</p>			Yes		Ramp Width LT (in)		60.0	Yes	Ramp Width RT (in)	60.0
			Yes		Ramp Slope LT (%)		6.3	Yes	Ramp Slope RT (%)	0.4
			Yes		Ramp XSlope LT (%)		1.7	No	Ramp XSlope RT (%)	5.8
			N/A		Landing Length (in)		N/A	N/A	DWS Provided?	N/A
			N/A		Landing Width (in)		N/A	N/A	DWS Contrast?	N/A
			N/A		Landing Slope (%)		N/A	N/A	DWS Length (in)	N/A
			N/A		Landing X Slope (%)		N/A	N/A	DWS Full Width?	N/A
			N/A		Landing Curb? (Y/N)		N/A	N/A	DWS Offset (in)	N/A
			N/A		Shared Landing?		N/A			
			N/A		Gutter Ponding?		N/A	N/A	Gutter Slope (%)	N/A
			N/A		Gutter Lip Ht (in)		N/A	N/A	Gutter X Slope (%)	N/A
			N/A		Painted X Walk1?		No	N/A	Painted X Walk2?	No
					X Walk 1 Direction		To NE		X Walk 2 Direction	To NW
			N/A		X Walk 1 Width (in)		N/A	N/A	X Walk 2 Width (in)	N/A
					X Walk 1 Slope (%)		5.7		X Walk 2 Slope (%)	1.2
					X Walk 1 X Slope (%)		0.1		X Walk 2 X Slope (%)	5.9
			N/A		Ramp inside XWalk1?		N/A	N/A	Ramp inside XWalk2?	N/A
					Road Slope (%)		3.5	N/A	Clear Space?	N/A
					Road X Slope (%)		6.2	N/A	Clear Space to XWalk (in)	N/A
			N/A		Any Obstructions?		N/A	N/A	Storm Grate/Utility Hazard?	N/A
					Obstruction Type				Storm Grate/Utility Type	
								N/A		N/A
								Yes	Surface Condition? (G/P)	Good
								Compliant	Curb Slope (%)	1.2

Total Cost: \$ 3200.00

