

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 7973 Main Street: HOVIS\_RD Cross Street: TAR\_HEEL\_RD Location: SW **Overall Compliance: No** ADA ID: 5B6319C6A176 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 21.25

**Codes/Mitigation Info/Possible Solution** 



THE RESERVE TO SERVE THE PARTY OF THE PARTY	THE STREET OF STREET, SALES
Street 1 Name	TAR HEEL RD
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

	Possible Solutions:						
The same of	Remove & Replace Entire Ramp.						
í							
ı							
ı	Surveyor Notes:						
	Surveyor Notes:						
ĺ	N/A						
	PROW/ADA:						
ı	Not Found, R304.5.1, R304.2.2						
	Not i ouiiu, 1304.5.1, 1304.2.2						
_							

	4625 9,075 K
	A)



Total Cost:



1850.00

Field Measurements/Component Compliance										
Compliance Description		Data	Comp	liance	Description	Data				
N/A	Ramp Length (in)	49.0	No	Ramp	Slope (%)	10.9				
No	Ramp Width (in)	38.0	Yes	Ramp	XSlope (%)	0.9				
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A				
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A				
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A				
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A				
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A				
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A				
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A				
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A				
N/A	Shared Landing?	N/A								
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A				
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A				
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A				
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A				
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A				
	X Walk 1 Slope (%)	0.2		X Wa	lk 2 Slope (%)	N/A				
	X Walk 1 X Slope (%)	6.6		X Wa	lk 2 X Slope (%)	N/A				
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A				
	Road Slope (%)	6.6	N/A	Clear	Space?	N/A				
	Road X Slope (%)	0.2	N/A	Clear	Space to XWalk (in)	N/A				
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A				
	Obstruction Type			Storm	Grate/Utility Type					
		N/A				N/A				
			Yes	Surfa	ce Condition? (G/P)	Good				