


# Access Compliance Report

## Public Rights-of-Way (Curb Ramps)

Intersection ID: 10024552	Main Street: D_DUCKS_LN	Cross Street: N/A	Location: NE
ADA ID: 5B7828A253BA	Ramp Type: BlendTrans1	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 33.75			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:						
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.						
	Surveyor Notes:						
	N/A						
	PROW/ADA:						
	Not Found, R304.5.1, R304.5.3						
	Street 1 Name	D DUCKS LN					
	Stop Condition-Street 1	None					
	Street 2 Name	N/A					
	Stop Condition-Street 2	StopSign					
	Total Cost:	\$ 3200.00					
				Compliance	Description	Data	Compliance
				Description			Description
				Data			Data
				N/A	Ramp Length (in)	50.5	Yes
				No	Ramp Width (in)	38.0	No
				N/A	Flare Type LT	N/A	N/A
				N/A	Flare Slope LT (%)	N/A	N/A
				N/A	Flare Traversable LT?	N/A	N/A
				N/A	Landing Length (in)	N/A	N/A
				N/A	Landing Width (in)	N/A	N/A
				N/A	Landing Slope (%)	N/A	N/A
				N/A	Landing X Slope (%)	N/A	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A
				N/A	Shared Landing?	N/A	N/A
				N/A	Gutter Ponding?	N/A	N/A
				N/A	Gutter Lip Ht (in)	N/A	N/A
				N/A	Painted X Walk1?	No	N/A
					X Walk 1 Direction	To W	
					X Walk 1 Width (in)	N/A	
					X Walk 1 Slope (%)	4.6	
					X Walk 1 X Slope (%)	1.4	
				N/A	Ramp inside XWalk1?	N/A	N/A
					Road Slope (%)	6.2	
					Road X Slope (%)	6.9	N/A
				N/A	Any Obstructions?	N/A	N/A
					Obstruction Type		
						N/A	N/A
						Yes	Surface Condition? (G/P)
						No	Curb Slope (%)
							Good
							5.2

