

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 21123 Main Street: RUTHERFORD DR Cross Street: SHARON\_RD Location: NW ADA ID: 5B8A6DE02FC2 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5

**Codes/Mitigation Info/Possible Solution** 



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 RUTHERFORD DR StopSign **SHARON RD** None

Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2

Total Cost: 3200.00

Field Measurements/Component Compliance						
Compliance Description		Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	40.0	No	Ramp	Slope (%)	10.6
Yes	Ramp Width (in)	58.0	Yes	Ramp	XSlope (%)	0.9
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	Yes	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Walk 1 Direction	To SW		X Wa	lk 2 Direction	To SE
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.8		X Wa	lk 2 Slope (%)	3.9
	X Walk 1 X Slope (%)	0.9		X Wa	lk 2 X Slope (%)	0.0
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	1.5	N/A	Clear	Space?	N/A
	Road X Slope (%)	2.2	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obstruction Type			Storm	Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





