## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29787 Main S		reet: FIDDLERS_ROOF_LN	Cross S	Street:	MILLWRIGHT_LN	Location:	SE		
ADA ID: 5C0DE3A4C90E Ramp T		ype: PerpDiag	Initial P	nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Act		Possible Solutions:		Compliance Description			Data Compliance Description		
10.		Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	57.0	No	Ramp Slope (%)	9.9
	A Charles and	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	38.0	Yes	Ramp XSlope (%)	0.7
the second states and				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	Star Land			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
<u>ዜ</u> ዜ	L. 6. 6.	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
NI 2000				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		4		N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To W
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	1 Name MILLWRIGHT LN				X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	2.4
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	1.1
Street 2 Name	FIDDLERS ROOF LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	2.1	N/A	Clear Space?	N/A
					Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

