

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.3

2.4

N/A

Good

Intersection ID: 9733 Main Street: LARRY DR Cross Street: TUCKASEEGEE RD Location: Ε **Overall Compliance: No** 10 ADA ID: 5C2F18B66757 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Flare Traversable RT?

Data

52.0

47.5

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Flare Traversable LT?



Possible Solutions:	Compli	ance	Description
Remove & Replace Entire Ramp.	N/A	Ramp	Length (in)
·	No	Ramp	Width (in)
	N/A	Flare	Type LT
	N/A	Flare	Slope LT (%)
	N/A	Flare	Traversable LT
	N/A	Landi	ng Length (in)
Surveyor Notes:	N/A	Landi	ng Width (in)
N/A	N/A	Landi	ng Slope (%)
	N/A	Landi	ng X Slope (%
	N/A	Landi	ng Curb? (Y/N
	N/A	Share	ed Landing?
PROW/ADA:	N/A	Gutte	er Ponding?
Not Found, R304.5.1, R304.5.3	N/A	Gutte	r Lip Ht (in)
	N/A	Paint	ed X Walk1?
		X Wa	lk 1 Direction
	N/A	X Wa	lk 1 Width (in)
		X Wa	lk 1 Slope (%)
		X Wa	lk 1 X Slope (%
	N/A	Ramp	inside XWalk

	VII.



