


Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: TUCKASEEGEE_RD Cross Street: N_I-85_RA Location: SE

ADA ID: 5C8A2BE3EBA0 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5

Codes/Mitigation Info/Possible Solution



Street 1 Name

N I-85 RA
Stop Condition-Street 1

None
Street 2 Name

N/A
Stop Condition-Street 2

N/A

Possible Solution	
Possible Solutions:	Col
Remove & Replace Entire Ramp.	N/A
·	Yes
	No
	No
	N/A
	N/A
Surveyor Notes:	N/A
PONDING	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
R304.2.2, R304.5.3	N/A
	N/A
	N/A
	N/A





Total Cost:



1600.00

Field Measurements/Component Compliance						
Comp	liance Description	Data	Comp	liance Description	Data	
N/A	Ramp Length (in)	135.5	N/A	Grade Break?	N/A	
Yes	Ramp Width (in)	61.0	N/A	Grade Break Slope (%)	0.0	
No	Ramp Slope (%)	12.4	N/A	Grade Break XSlope (%)	0.0	
No	Ramp XSlope (%)	5.7				
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	Yes		Road Slope (%)	6.9	
	X Walk 1 Direction	To NW		Road X Slope (%)	5.9	
	X Walk 1 Width (in)	112.0		Clear Space?	N/A	
	X Walk 1 Slope (%)	6.9	N/A	Clear Space to XWalk (in)	N/A	
	X Walk 1 X Slope (%)	5.9	N/A	Storm Grate/Utility Hazard?	N/A	
N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type		
N/A	Any Obstructions?	N/A			N/A	
	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
		N/A	N/A	Curb Slope (%)	1.6	